

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

1562  
NW  
> 1  
1.974 mi.  
10424 ft.

62 PRECINCT NYPD -DDC  
1925 BATH AVENUE  
BROOKLYN, NY

NY LTANKS  
NY AST  
NY Spills  
U001839405  
N/A

Relative:  
Higher

Actual:  
0 ft.

LTANKS:

Name: 62 PRECINCT NYPD -DDC  
Address: 1925 BATH AVENUE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9407869 / 2001-08-09  
Facility ID: 9407869  
Site ID: 235180  
Spill Date: 1994-09-12  
Spill Cause: Tank Failure  
Spill Source: Non Major Facility > 1,100 gal  
Spill Class: C3  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: JMKRIMGO  
Referred To: Not reported  
Reported to Dept: 1994-09-13  
CID: Not reported  
Water Affected: Not reported  
Spill Notifier: Federal Government  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: False  
UST Involvement: False  
Remediation Phase: 0  
Date Entered In Computer: 1994-10-27  
Spill Record Last Update: 2004-12-22  
Spiller Name: Not reported  
Spiller Company: 62ND POLICE STATION  
Spiller Address: 1925 BATH AVENUE  
Spiller County: 001  
  
Spiller Contact: Not reported  
Spiller Phone: Not reported  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 193711  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was

Remarks:

KRIMGOLD // : REASSIGNED FROM SIGONA TO CLAUDIA GUITIERREZ ON 04/25/95. 04/25/95: REASSIGNED FROM SIGONA TO DANIEL WEISSMAN ON 04/25/95. Investigation and cleanup completed by URS Corp. See DDC file. "  
"TAKING SAMPLES, FOUND CONTAMINATED SOIL- WILL EXCAVATE. DEC SIGONA HAD NOT RESPONDED TO SITE, REQUESTS REFERRAL TO DGS MONITORS."

All TTF:

Facility ID: 9407869  
Spill Number: 9407869  
Spill Tank Test: 1543140  
Site ID: 235180  
Tank Number: Not reported  
Tank Size: 0  
Material: 0066A  
EPA UST: Not reported  
UST: Not reported  
Cause: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Source: Not reported  
Test Method: 00  
Test Method 2: Unknown  
Leak Rate: .00  
Gross Fail: Not reported  
Modified By: Spills  
Last Modified Date: Not reported

All Materials:

Site ID: 235180  
Operable Unit ID: 1005574  
Operable Unit: 01  
Material ID: 377328  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: -1.00  
Units: L  
Recovered: .00  
Oxygenate: Not reported

AST:

Name: 62 PCT  
Address: 1925 BATH AVENUE  
City,State,Zip: BROOKLYN, NY 11214  
Region: STATE  
DEC Region: 2  
Site Status: Unregulated/Closed  
Facility Id: 2-342858  
Program Type: PBS  
UTM X: 584354.47755  
UTM Y: 4495063.62352  
Expiration Date: N/A  
Site Type: Other

Affiliation Records:

Site Id: 16654  
Affiliation Type: Facility Owner  
Company Name: NYCPD/ASO  
Contact Type: Not reported  
Contact Name: Not reported  
Address1: 1 POLICE PLAZA - ROOM 800  
Address2: Not reported  
City: NEW YORK  
State: NY  
Zip Code: 10038  
Country Code: 001  
Phone: (718) 476-6888  
EMail: Not reported  
Fax Number: Not reported  
Modified By: NRLOMBAR  
Date Last Modified: 2014-02-21

Site Id: 16654  
Affiliation Type: Mail Contact  
Company Name: NYC POLICE DEPARTMENT  
Contact Type: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Contact Name: SGT. BRENDAN MORAN  
Address1: BUILDING MAINTENANCE SECTION  
Address2: 59-06 BROOKLYN-QUEENS EXPRESSWAY  
City: WOODSIDE  
State: NY  
Zip Code: 11377  
Country Code: 001  
Phone: (718) 476-6888  
EMail: BRENDON.MORAN@NYPD.ORG  
Fax Number: Not reported  
Modified By: NRLOMBAR  
Date Last Modified: 2014-02-21

Site Id: 16654  
Affiliation Type: Facility Operator  
Company Name: 62 PCT  
Contact Type: Not reported  
Contact Name: SGT. BRENDAN MORAN  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 001  
Phone: (718) 476-6888  
EMail: Not reported  
Fax Number: Not reported  
Modified By: NRLOMBAR  
Date Last Modified: 2014-02-21

Site Id: 16654  
Affiliation Type: Emergency Contact  
Company Name: NYCPD/ASO  
Contact Type: Not reported  
Contact Name: SGT. BRENDAN MORAN  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 999  
Phone: (718) 476-6888  
EMail: Not reported  
Fax Number: Not reported  
Modified By: NRLOMBAR  
Date Last Modified: 2014-02-21

Tank Info:

Tank Number: 001  
Tank Id: 32279  
Material Code: 0001  
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None  
G03 - Tank Secondary Containment - Vault (w/o access)  
K01 - Spill Prevention - Catch Basin

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

L09 - Piping Leak Detection - Exempt Suction Piping  
A00 - Tank Internal Protection - None  
B01 - Tank External Protection - Painted/Asphalt Coating  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
F00 - Pipe External Protection - None  
C01 - Pipe Location - Aboveground  
I04 - Overfill - Product Level Gauge (A/G)  
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)  
J02 - Dispenser - Suction Dispenser  
H05 - Tank Leak Detection - In-Tank System (ATG)  
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.  
Tank Type: Steel/Carbon Steel/Iron  
Tank Status: Closed - In Place  
Pipe Model: Not reported  
Install Date: 08/01/1961  
Capacity Gallons: 2500  
Tightness Test Method: 21  
Date Test: 05/15/2012  
Next Test Date: Not reported  
Date Tank Closed: 01/22/2014  
Register: True  
Modified By: NRLOMBAR  
Last Modified: 04/14/2017  
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 003  
Tank Id: 240856  
Material Code: 0001  
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None  
I02 - Overfill - High Level Alarm  
K01 - Spill Prevention - Catch Basin  
L09 - Piping Leak Detection - Exempt Suction Piping  
G01 - Tank Secondary Containment - Diking (Aboveground)  
F00 - Pipe External Protection - None  
A00 - Tank Internal Protection - None  
B01 - Tank External Protection - Painted/Asphalt Coating  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring  
C01 - Pipe Location - Aboveground  
J02 - Dispenser - Suction Dispenser  
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.  
Tank Type: Steel/Carbon Steel/Iron  
Tank Status: Closed - Removed  
Pipe Model: Not reported  
Install Date: 08/01/1961  
Capacity Gallons: 25  
Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Date Tank Closed: 01/22/2014  
Register: True  
Modified By: NRLOMBAR  
Last Modified: 04/14/2017

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material Name: #2 fuel oil (on-site consumption)

SPILLS:

Name: 62 PRECINCT NYPD -DDC  
Address: 1925 BATH AVENUE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9501517 / 2001-08-09  
Facility ID: 9501517  
Facility Type: ER  
DER Facility ID: 193711  
Site ID: 185281  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C3  
SWIS: 2401  
Spill Date: 1995-05-05  
Investigator: JMKRIMGO  
Referred To: Not reported  
Reported to Dept: 1995-05-05  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Institutional, Educational, Gov., Other  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1995-05-22  
Spill Record Last Update: 2004-12-22  
Spiller Name: Not reported  
Spiller Company: CAPITAL FUEL  
Spiller Address: 162 20TH AVENUE  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
KRIMGOLD Investigation and cleanup completed by URS Corp. See DDC  
file."

Remarks: "BROKEN GAUGE ON TANK AND NO VENT ALARM SPILL IS BEING CLEANED UP.  
TANK GAUGE WAS FAULTY"

All Materials:

Site ID: 185281  
Operable Unit ID: 1015914  
Operable Unit: 01  
Material ID: 370123  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 30.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Name: 62 PRECINCT NYPD -DDC  
Address: 1925 BATH AVENUE

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9508737 / 1995-10-17  
Facility ID: 9508737  
Facility Type: ER  
DER Facility ID: 193711  
Site ID: 185282  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 1995-10-16  
Investigator: WEISSMAN  
Referred To: Not reported  
Reported to Dept: 1995-10-17  
CID: 257  
Water Affected: Not reported  
Spill Source: Institutional, Educational, Gov., Other  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1995-10-17  
Spill Record Last Update: 2004-12-22  
  
Spiller Name: JANIET  
Spiller Company: 63RD PCT POLICE DEPT  
Spiller Address: 1925 BATH AVE  
Spiller Company: 001  
Contact Name: JANIET  
DEC Memo: ""  
Remarks: "CALLER WAS HIRED TO CLEANUP TANK AND TEST THEY FOUND A SMALL AMOUNT OF SOME TYPE OF OILLY PRODUCT "  
  
All Materials:  
Site ID: 185282  
Operable Unit ID: 1019314  
Operable Unit: 01  
Material ID: 359698  
Material Code: 0064A  
Material Name: unknown material  
Case No.: Not reported  
Material FA: Other  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported